GF00.19-P-3000-02DA	Arrangement and assignment of Z connector	MODEL 211	
	sleeves (cable connections in wiring harness)		
	- engine compartment right		



P00.19-2836-09

Z connec-	Designation		Component	Designation	Plug Pin
or sieeve					
Z6/27	Sensor ground connector sleeve	Z	N3/10	ME-SFI [ME] control module	3.6
		!	G3/3	Left O2 sensor upstream TWC [KAT]	3
		!	G3/4	Right O2 sensor upstream TWC [KAT]	3
Z6/49	Ground (W2) connector sleeve				
	LHD	z	W2	Ground (at right headlamp unit)	
	KKLA	!	B32/2	C-AAC sun sensor (4 in total)	1
	RL	!	E1	Left front headlamp unit	S2.1
					S3.1
	LL	!	E2	Right front headlamp unit	S2.1
	RL	!			S3.1
	Xenon	!			S4.1
	RL	!	E5/2	Right fog lamp	1
	LL	!	M13	Coolant circulation pump	2
		!	S10/2	Right front brake pad contact sensor	
Z6/49 (1)	Ground (W2) connector sleeve				
	RHD	z	W9	Ground (at left headlamp unit)	
	RL	!	M5/1	Windshield washer fluid pump	2
	RL	!	R2/1	Washer nozzle heater	1.1
					2.1
	RL	!	R2/11	Washer nozzle hose heater	1
	LL	!	H2	Fanfare horns	1
Z6/50(1) (Ground (W9) connector sleeve	z	W9	Ground (at left headlamp unit)	
	LL		M5/1	Windshield washer fluid pump	2
	LL	!	N47-5	ESP, SPS and BAS [ESP, PML and BAS] control module	1.23
	LL	,	R2/1	Washer nozzle heater	1.1
		•	112/1	Tradition field field field	2.1
	LL	,	R2/11	Washer nozzle hose heater	1
	! 02/03		S11	Brake fluid indicator switch	1
	RL		E1	Left front headlamp unit	S2.1
		-	= •		S3.1
	RL	!	E2	Right front headlamp unit	S2.1
		•			S3.1
	RL	!	E5/1	Left fog lamp	1
Z7/24		z	K57/2	Auxiliary battery relay	2
	S. San St Connector Stocks	_	101/2	Turning Sullery Tolay	1.1

! F30 Second battery additional fuse